• PRINTER I

PRINTER RUSH (PTO ASSISTANCE)

Application : / <u>0/005/2</u>	Examiner : 🔇	Rinley	GAU:	2852		
From: TiNCGill	1	D FMF FDC	Date:	5-20-05		
Tracking #: 29M /0/065/21 Week Date: 4-4-05						
DOC CODE 1449 1DS CLM IIFW SRFW DRW OATH 312	P-22-03	MISCELL Continuing Foreign Price Document I Fees Other	Data ority			
[RUSH] MESSAGE: Page 22 Of specification ends incomplete. It does not end with a period.						
[XRUSH] RESPONSE: Contract						
			INI	TIALS: V		

NOTE: This form will be included as part of the official USPTO record, with the Response document coded as XRUSH.

REV 10/04

[Table 5]

Process Item		No Start-up used	Grain size larger than regulation	
1	Electrified amount of toner on developer carrier (µC/g)	-21.56	-18.32	
2	Toner carrying property (printing density OD)	1.376	1.421	
3	Unevenness in toner carrying property (variations in printing density)	0.014	0.017	
4	Toner grain size (on developer carrier)	7.94	8.46	
5	Printing density difference (OD) after printing 0 to 1000 sheets	0.053	0.027	

When the toner grain size contained in the start-up toner was set larger than the regulation of the present invention, the variations in printing density within sheets were increased although the improvement in initial printing density and the suppression of the printing density difference (fluctuation) in running could be attained, and the effect was consequently insufficient.

[Comparative Example 5]

Insufficient filling amount of start-up... 15 g of toner B used in Example 1 is filled,

10